



WELL COMPLETION REPORT

NEW REHAB FILTER

CONSTRUCTED BY LWI – Angola
(Who built the well?)

SPONSORED BY: LWI
(Donor Sponsor name if other than LWI-who paid for the well?)

DATE OF WELL COMPLETION: July 30, 2008

COUNTRY: Angola

LOCATION: ELCIN church, Omundangilo, Cunene
(Name of project, village or town)

GPS: 17 25 . 472 _ _ N S , 016 42 . 223 _ _ E W

(The E/W may have up to 3 digits to begin but may only have two)

GPS 29 37.93333 N S , 95 34.20833 E W
(Example: Living Water International, Stafford, TX)

PROJECT NUMBER: AG080630VTL0808013020BYPNW
(To be supplied by LWI)

LIVING WATER INTERNATIONAL WELL COMPLETION REPORT

Information should be in Metric

Completed Project Information

Altitude	<u>3602</u>
Total Depth	<u>21</u>
Static Level	<u>6</u>
Diameter of Casing--100mm = 4", 150mm = 6" , or 200mm = 8"	<u>110</u>
Start of Screen <u>10</u>	Stop of Screen <u>18</u>
Casing Material (Select one)	PVC <input checked="" type="checkbox"/> Steel <input type="checkbox"/>
Pump Type (Select one)	Submersible <input type="checkbox"/> IndiaMarkII <input type="checkbox"/> AFRIDEV <input type="checkbox"/> Other <input checked="" type="checkbox"/>
Depth of Cylinder	<u>12</u>
Liters Per Minute	<u>110</u>
Health & Hygiene (Check if completed)	<input checked="" type="checkbox"/>

Identification of Problems

Please describe:

The present primary source of water is variable. When there is power the cistern has water because the borehole has an electric pump. There is an extremely hand dug well and a small water catchment source about 500 meters away that may last another couple of weeks. Another kilometer down the road is another water catchment, already turned green.

People Served (Enter number of people, not families) 950

Final Well Construction

WELL SEAL

Yes No

If 'No,' please explain:

WELL PAD CONSTRUCTION

UNICEF Standard: Yes No

If 'No,' please explain:

DISINFECTION OF THE WELL

Yes No

If 'No,' please explain:

Description

Please write a narrative description of the following:

GENERAL INFORMATION

The community is baffled by the water found at this site. Recently the community took the church property away from ELCIN, because the community elders wanted to use it for something else. The church has no say in the matter, other than they will take their building with them. We encouraged the church leaders to leave the building alone and give it to the community to use as they see fit. We pointed out that the "bad" property they were given is blessed with water!

The school principal, several teachers, and many children came in the afternoon after school let out to ask if they could drink this water. Yes! Drink and be satisfied with clean water! They are happy now that there will be clean water to drink everyday as they go to and come home from school.

TESTIMONIAL/EVANGELISM

The church is central to most communities. The pastor is now convinced we are interested in helping him build up the church using wells as a tool to draw people to Christ. This well site is the best one so far for this area. The pastor attributes this fact to the frequent prayer meetings held by the elders at this specific place. The original church was occupied by the boers during the war. The church was destroyed when the conflict ended in 1990. A new building was constructed over the last 6 years. This well is a wonderful example of God's love that prevails through all things, even war.

HYGIENE TEACHING

Women and children instructed on proper use of water.

WRITTEN BY: H. Gary Wilkins
(Who wrote this report?)

DATE: August 3., 2008









